


**GOVERNMENT OF ARUNACHAL PRADESH
PUBLIC WORKS DEPARTMENT**



**OFFICE OF THE ASSISTANT ENGINEER
PASIGHAT SUB-DIVISION No.II :: PWD**


TO WHOM IT MAY CONCERN

The undersigned along with the Junior Engineer concerned inspected the "Kendriya Vidyalaya School Building, Pasighat East Siang District, A.P." on 08/08/2019. In this regard it is to certify that the School building is structurally sound and safe for conducting classes.

Further it is suggested to undertake the following works under maintenance :

1. Special repairs of toilets.
2. Repairs/replacement of floors with cota stone of first floor.
3. Repairs of doors and windows.
4. Painting works.

Date : 08/08/2019
Place :- Pasighat


(Er. Keni Zirido)
Assistant Engineer
Pasighat Sub-Division No.II
P.W.D., A.P.
P.W.D. Pasighat, A. P.